
Appendix B – Potentiometric Surface Maps 2001 – 2002

- AIR MONITORING STATIONS
- **EXTRACTION WELLS**
- . VILLAGE PRODUCTION WELLS
- OBSERVATION WELL
- \* ELEV. NOT USED IN CONTOURING
- GROUNDWATER DIVIDE

# onresponsi



GRANVILLE SOLVENTS SITE POTENTIOMETRIC SURFACE AUGUST 22, 2001 GRANVILLE, OHIO

FILE NAME CHECKED DRAWN DATE PROJECT NO. FIGURE POTAUGO

- MONITOR WELLS
- # AIR MONITORING STATIONS
- R EXTRACTION WELLS
- · VILLAGE PRODUCTION WELLS
- @ OBSERVATION WELL
- \* ELEV.. NOT USED IN CONTOURING
- GROUNDWATER DIVIDE

# onresponsi



Metcalf & Eddy

GRANVILLE SOLVENTS SITE POTENTIOMETRIC SURFACE NOVEMBER 17, 2001

GRANVILLE, OHIO

FILE NAME CHECKED DRAWN DATE PROJECT NO. FIGURE POTNOVO1 016688

- AIR MONITORING STATIONS
- EXTRACTION WELLS
- . VILLAGE PRODUCTION WELLS
- A OBSERVATION WELL
- \* ELEV. NOT USED IN CONTOURING
- GROUNDWATER DIVIDE

# onresponsi



GRANVILLE SOLVENTS SITE POTENTIOMETRIC SURFACE **DECEMBER 12, 2001** 

GRANVILLE, OHIO

FILE NAME CHECKED DRAWN DATE PROJECT NO. FIGURE POTDECO JAW 016688 3-3

- AR MONITORING STATIONS
- **B EXTRACTION WELLS**
- · VILLAGE PRODUCTION WELL'S
- @ OBSERVATION WELL
- \* ELEV. NOT USED IN CONTOURING

# nonresponsive



Metcalf & Eddy

GRANVILLE SOLVENTS SITE POTENTIOMETRIC SURFACE **JANUARY 16, 2002** 

GRANVILLE, ÓHIO

FILE NAME	CHECKED	DRAWN	DATE	PROJECT NO.	FIGURE
POTJANO2	JP:	JAW	1	016688	3-4

- . MONITOR WELLS
- AIR MONITORING STATIONS
- **EXTRACTION WELLS**
- . VILLAGE PRODUCTION WELLS
- D OBSERVATION WELL
- \* ELEV. NOT USED IN CONTOURING

--- GROUNDWATER DIVIDE

# nonresponsive

SCALE IN FEET 0 100' 200



Metcalf & Eddy

GRANVILLE SOLVENTS SITE
POTENTIOMETRIC SURFACE

FEBRUARY 13, 2002

GRANVILLE, OHIO

FILE NAME CHECKED DRAWN DATE PROJECT NO. FIGURE
POTFEB02 JP JAW - 016688 3-5